

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K0000	<p>A Life Safety Code Recertification, State Licensure and Quality Assurance Walk-thru Survey were conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 09/04/12</p> <p>Facility Number: 012225 Provider Number: 155780 AIM Number: 200983560</p> <p>Surveyor: Mark Caraher, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, Madison Health Care Center was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type III (200) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. The facility has battery operated</p>		K0000	<p><b>This plan of correction is to serve as Madison Health Care Centers' credible allegation of compliance.</b></p> <p><b>Submission of this plan of correction does not constitute an admission by Madison Health Care Center or its' management company that the allegations contained in the survey report are a true and accurate portrayal of the provision of nursing care and other services in this facility. Nor does this submission constitute an agreement or admission of the survey allegations.</b></p>			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>smoke detectors in all resident sleeping rooms. The facility has a capacity of 130 and had a census of 62 at the time of this visit.</p> <p>The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage.</p> <p>All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered except for the detached shed providing facility storage.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 09/06/12.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following:</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0029 SS=B	<p>NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with ¾ hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1</p> <p>Based on observation and interview, the facility failed to ensure 1 of 2 kitchen doors opening into the service corridor closed automatically or upon activation of the fire alarm system. Furthermore, doors to hazardous areas are required to latch into the door frame when closed to keep the door tightly closed to resist the passage of smoke. This deficient practice could affect staff and visitors in the vicinity of the kitchen exit doors in the service corridor.</p> <p>Findings include:</p> <p>Based on observation with the Maintenance Director during a tour of the facility from 11:20 a.m. to 2:00 p.m. on 09/04/12, the west door in the set of two kitchen exit doors to the service corridor was in the fully open position and not equipped with a self closer or automatic</p>			K0029	<p>K 029 It is the policy of the facility to provide self-closing doors that will automatically close upon fire alarm system activation. The door identified was in the service hallway into the kitchen. This is an employee area of the building only. An outside contractor has provided a bid to the facility to get the equipment, supplies, and labor to fix the door. The bid has been approved by the facility. The outside contractor has ordered the parts and has confirmed that the work can be completed by October 15, 2012. All self-closing doors will be checked monthly basis with the fire drills to ensure the doors automatically release with the fire alarm activation. This will be documented on the fire drill report form. The Quality Assurance Committee will monitor by reviewing the fire drill reports monthly for continued compliance.</p>		10/15/2012

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>door closer or a positive latching mechanism to latch the door into the door frame. Based on interview at the time of observation, the Maintenance Director stated the west door is normally kept closed and locked into the door frame with a bolt at the top of the door and is only opened to bring food carts into and out of the kitchen, but acknowledged the west door in the set of two kitchen doors opening into the service corridor did not self close and latch into the door frame.</p> <p>3.1-19(b)</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0048 SS=B	<p>NFPA 101 LIFE SAFETY CODE STANDARD</p> <p>There is a written plan for the protection of all patients and for their evacuation in the event of an emergency. 19.7.1.1</p> <p>Based on record review and interview, the facility failed to include the use of kitchen fire extinguishers in 1 of 1 written fire safety plans for the facility. LSC 19.7.2.2 requires written health care occupancy fire safety plans shall provide for the following:</p> <p>(1) Use of alarms (2) Transmission of alarm to the fire department (3) Response to alarms (4) Isolation of fire (5) Evacuation of immediate area (6) Evacuation of smoke compartment (7) Preparation of floors and building for evacuation (8) Extinguishment of fire</p> <p>This deficient practice affects staff and visitors in the vicinity of the kitchen.</p> <p>Findings include:</p> <p>Based on review of the "Fire Prevention" and "General Action Fire Plan" documentation with the Maintenance Director during record review from 9:30 a.m. to 11:20 a.m. on 09/04/12, the facility's written fire safety plan did not address the use of ABC type fire extinguishers and the K-class fire</p>			K0048	<p>K048 It is the policy of the facility to have a written plan for the protection of all residents in the event of an emergency. The written fire plan for the facility has been revised by the Administrator for the use of the K-class fire extinguishing system in relationship with the use of the kitchen hood extinguishing system. The revised changes to the plan were reviewed at an education session with all staff on 9-7-12. The safety committee will review the fire and disaster plan on a quarterly basis to ensure that all policies protect the residents in the event of an emergency. The monthly safety committee minutes will be reviewed by the Quality Assurance Committee to ensure continued compliance. Correction Date 9-7-12</p>		09/07/2012

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>extinguisher located in the kitchen in relationship with the use of the kitchen overhead extinguishing system. Based on interview at the time of record review, the Maintenance Director acknowledged the written fire safety plan for the facility did not include the policy to activate the overhead hood extinguishing system to suppress a fire before using either the ABC type fire extinguisher or the K-class fire extinguisher.</p> <p>3.1-19(b)</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K0052 SS=F	<p>NFPA 101 LIFE SAFETY CODE STANDARD A fire alarm system required for life safety is installed, tested, and maintained in accordance with NFPA 70 National Electrical Code and NFPA 72. The system has an approved maintenance and testing program complying with applicable requirements of NFPA 70 and 72. 9.6.1.4</p> <p>1. Based on observation and interview, the facility failed to maintain 1 of 71 smoke detectors in accordance with NFPA 72. NFPA 72, 2-3.5.1 requires in spaces served by air handling systems, smoke detectors shall not be located where airflow prevents operation of the detectors. NFPA 72, A-2-3.5.1 explains smoke detectors should not be located in a direct airflow nor closer than 3 feet from an air supply diffuser or return air opening. This deficient practice could affect 28 residents, staff or visitors in the vicinity of the Kennedy Cove smoke wall cross corridor door set.</p> <p>Findings include:</p> <p>Based on observation with the Maintenance Director during a tour of the facility from 11:20 a.m. to 2:00 p.m. on 09/04/12, the smoke detector in the corridor next to the Kennedy Cove smoke wall cross corridor door set was located on the ceiling within one foot of an air supply vent. Based on interview at the time of observation, the Maintenance</p>		K0052	<p>K052 It is the policy of the facility to place and maintain smoke detectors in accordance with NFPA72. 1) This deficient practice could affect an area that has 28 resident beds. An outside contractor has provided a bid to the facility to get one smoke detector moved that is within 3 feet from a return air opening. The bid has been approved by the facility. The outside contractor has confirmed that the work can be completed by October 15, 2012. The maintenance supervisor will inspect all the smoke detectors on a monthly basis. The smoke detectors are part of the preventative maintenance program. The Quality Assurance Committee will monitor by reviewing the preventative maintenance logs quarterly. 2) A outside contractor has come into the building to performed the sensitivity testing on the 7 smoke detectors that were identified in the attic. Per National Fire Alarm Code NFPA 72, 7-3.2 the sensitivity testing will be completed every alternate year. The maintenance supervisor will</p>		10/15/2012	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>Director acknowledged the smoke detector in the corridor next to the Kennedy Cove smoke wall cross corridor door set was located on the ceiling within one foot of an air supply vent.</p> <p>3.1-19(b)</p> <p>2. Based on record review, observation and interview; the facility failed to ensure 7 of 71 smoke detectors were maintained in accordance with the applicable requirements of NFPA 72, National Fire Alarm Code. NFPA 72, 7-3.2 requires detector sensitivity shall be checked within 1 year after installation and every alternate year thereafter. After the second required calibration test, if sensitivity tests indicate the detector has remained within its listed and marked sensitivity range (or 4 percent obscuration light gray smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. If the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or in areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. To ensure each smoke detector is within its listed and marked sensitivity range, it shall be tested using any of the following</p>				<p>monitor testing of all smoke detectors. The results of smoke detector testing will be reviewed by the Quality Assurance Committee for continued compliance.</p>		



STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
	<p>methods:</p> <p>(1) Calibrated test method</p> <p>(2) Manufacturer's calibrated sensitivity test instrument</p> <p>(3) Listed control equipment arranged for the purpose</p> <p>(4) Smoke detector/control unit arrangement whereby the detector causes a signal at the control unit where its sensitivity is outside its listed sensitivity range</p> <p>(5) Other calibrated sensitivity test methods approved by the authority having jurisdiction</p> <p>Detectors found to have a sensitivity outside the listed and marked sensitivity range shall be cleaned and recalibrated or be replaced. This deficient practice could affect all residents staff and visitors.</p> <p>Findings include:</p> <p>Based on review of SafeCare "Sensitivity Test &amp; Inspection Report" documentation dated 04/03/12 with the Maintenance Director during record review from 9:30 a.m. to 11:20 a.m. on 09/04/12, each of seven duct detectors located in the attic throughout the facility were listed as "NA" for the smoke detector sensitivity test. In addition, a review of SafeCare "Sensitivity Test &amp; Inspection Report" documentation dated 05/13/10 showed it has been more than two years since the</p>						

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155780		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 09/04/2012	
NAME OF PROVIDER OR SUPPLIER  MADISON HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 7465 MADISON AVE INDIANAPOLIS, IN 46227			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
	<p>seven duct detectors were last sensitivity tested. Based on observations with the Maintenance Director during a tour of the facility from 11:20 a.m. to 2:00 p.m. on 09/04/12, seven duct detectors are located in the attic throughout the facility. Based on interview at the time of record review, the Maintenance Director stated no documentation of attic duct detector sensitivity testing in the last two years was available for review and acknowledged it has been more than two years since the aforementioned duct detectors were sensitivity tested.</p> <p>3.1-19(b)</p>						